

FOG/SMOKE MACHINE INSTRUCTIONS

1. Insert remote control into rear of machine.
2. To avoid risk of electric shock, insert line cord plug into grounded outlet only.
3. Fill reservoir with water based Fog Solution.
4. Close cap tightly. Push clear plastic feeder tube down through the cap (if there is slack)
5. When the indicator light on the controller goes on, the machine is ready for use.
6. At times the indicator light will go off. This is NORMAL, the machine is simply recycling. Depress the switch only when indicator light is ON.
7. To use timer mode, press "TIMER" button. Adjust "DURATION" knob for length of fog burst. Adjust "INTERVAL" knob for length of time between fog bursts.
8. Allow fog machine to "COOL DOWN" before packing for transportation.

IMPORTANT

Always make sure that there is enough fog solution in the tank before turning the fog machine on. Activating the pump without fluid can cause damage to the pump and heat core.

CAUTION

Vapor from this fluid may be irritating to some persons with allergic sensitivity. Do not expose at close range to known asthmatic. Use in a well-ventilated area. To avoid injury from hot steam- **KEEP AWAY FROM NOZZLE AT LEAST 2 FEET.**